


# SANDOR


---




Dear Customer,

We design and produce our products for people to love and have fun with them as we do.

The product you bought was subjected to all sorts of tests and control before sending out to you.




Before start assembling, please check the whole components and accessories according to the lists. If you bought more than one product, to prevent confusion be sure that you completed the first product. Then start the other product's assembling.



Before start assembling, please clean all the components with a damp cloth. Also for usual cleaning, this will be enough.



Although all the products are produced and packed carefully, sometimes happen that some component is damaged during the transportation. In such a case please check the missing or damaged part and do not hesitate to contact us. You can send e-mail to [info@hobby.com](mailto:info@hobby.com) or reach us at [+353145511111](tel:+353145511111)









Do not use your furniture for out of purposes. If you would like to use it, please contact us for further questions.















Do not directly contact your furniture with excessive heat, cold and humidity because the product can be affected..

# ATTENTION !!


Minifix is the main connection material used in products. Before starting assembly, please check the drawings below.



# ACCESSORY LIST




<b>A23</b>  Minifix M8 28x	<b>A22</b>  Minifix G18 28x	<b>A04</b>  KVLY 24x	<b>C01</b>  DM 4x	<b>C02</b>  SDM 4x
<b>C04</b>  MA 8x	<b>A94</b>  SYH 4x	<b>A65</b>  RP 8x	<b>A17</b>  4x50 4x	<b>A18</b>  3,5x18 72x
<b>A06</b>  BYZ 28x	<b>R03</b>  CRY 1x	<b>A41</b>  4x30 12x	<b>A48</b>  AC 50x	

## GENERAL VIEW






1666.01	1	1600	400	18
1666.02	1	1600	400	18
1666.03	1	564	400	18
1666.04	1	564	400	18
1666.05	1	564	400	18
1666.06	1	564	400	18
1666.07	1	414	400	18
1666.08	1	800	400	18
1666.09	2	364	400	18
1666.10	1	796	126	18
1666.11	1	350	96	18
1666.12	1	350	96	18
1666.13	1	738	96	18
1666.14	1	576	396	18
1666.15	1	576	396	18
1666.16	1	426	396	18
1666.17	1	426	396	18
1666.18	2	1396	70	18
1666.19	2	196	70	18
1666.20	1	774	356	3
1666.21	2	1596	298	3

# 1






# 2





4

# 3




# 4




5


5




6



7




8




7



9



10



8